



KLEINFELDER

Bright People. Right Solutions.

APPENDIX B – PHOTOGRAPHS



PHOTO #1: INFLUENT MANHOLE WHILE FACING A NORTH WESTERLY DIRECTION



PHOTO #2: EXISTING HEADWORKS FACILITY WHILE FACING IN THE NORTHEAST DIRECTION



PHOTO #3: EXISTING HEADWORKS FACILITY



PHOTO #4: EXISTING HEADWORKS FACILITY



PHOTO #5: HEADWORKS FACILITY



PHOTO #6: HEADWORKS FACILITY



PHOTO #7: HEADWORKS FACILITY



PHOTO #8: HEADWORKS FACILITY



PHOTO #9: HEADWORKS FACILITY



PHOTO #10: PRIMARY CLARIFIER



PHOTO #11: PRIMARY CLARIFIER



PHOTO #12: ENTRANCE TO CONTROL BUILDING FACING WEST



PHOTO #13: SCREW PUMPS



PHOTO #14: SCREW PUMPS



PHOTO #15: CONTROL BUILDING FACING SOUTHWEST



PHOTO #16: MCC CABINETS WITH REMAINING WIRING AND CONTROL EQUIPMENT



PHOTO #17: CONDITION OF PUMP ROOM



PHOTO #18: AERATION BASIN AND INFLUENT DIFFUSER



PHOTO #19: MECHANICAL AERATORS



PHOTO #20: MECHANICAL AERATORS



PHOTO #21: DRIVE MOTORS



PHOTO #22: CONDITION OF SECONDARY CLARIFIER



PHOTO #23: CHLORINE CONTACT TANK CONDITION



PHOTO #24: UV DISINFECTION SYSTEM



PHOTO #25: JIB CRANE



PHOTO #26: REAR ENTRANCE TO THE SLUDGE DIGESTOR FACILITY



PHOTO #27: CONDITION OF COVER OVER PRIMARY DIGESTOR



PHOTO #28: COVER OF SECONDARY DIGESTOR



PHOTO #29: PUMP ROOM



PHOTO #30: TWO BOILERS



PHOTO #31: CONDITION OF THICKENER



PHOTO #32: CONDITION OF THICKENER



PHOTO #33: EXTERIOR OF BUILDING



PHOTO #34: CONDITION OF BUILDING



PHOTO #35: CONDITION OF BUILDING



PHOTO #36: CONDITION OF BUILDING



PHOTO #37: ONE OF THE BLOWERS AND SLUDGE PUMP



PHOTO #38: SLUDGE STORAGE TANK ADJACENT TO REAR OF OPERATIONS BUILDING



PHOTO #39: WATER STORAGE TANK



PHOTO #40: SOUTHEASTERLY DIRECTION OF BUILDING




PHOTO #41: INTERIOR OF BUILDING



PHOTO #42: INTERIOR OF BUILDING




PHOTO #43: INTERIOR OF BUILDING



PHOTO #44: INTERIOR OF BUILDING



PHOTO #45: INTERIOR OF BUILDING




PHOTO #46: INTERIOR OF BUILDING



PHOTO #47: INTERIOR OF BUILDING




PHOTO #48: INTERIOR OF BUILDING



PHOTO #49: INTERIOR OF BUILDING



PHOTO #50: DRYING BEDS



PHOTO #51: DRYING BEDS



PHOTO #52: DRYING BEDS



PHOTO #53: EXTERIOR OF SHED



PHOTO #54: EXTERIOR OF SHED



PHOTO #55: BLENDING AREA USED FOR YARD AND STREET DEBRIS



PHOTO #56: CONDITIONS OF LAGOON FACING SOUTH



PHOTO #57: CONDITIONS OF LAGOON FACING SOUTH



PHOTO #58: MAINTENANCE BUILDING VIEWED FROM SOUTH